



NTSB Identification: OAK75FJA06  
14 CFR Part 135 Nonscheduled operation of MURRAYAIR LTD.  
Aircraft: HILLER ACFT UH-12E, registration: N90474

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES				FLIGHT	PILOT DATA	
				F	S	M/N	PURPOSE			
3-4040	74/12/3	NR.KAPAAU,HAWAII	HILLER ACFT UH-12E	CR-	0	0	1	COMMERCIAL	COMMERCIAL, AGE 27, 3933	
			N90474	PX-	0	0	1	AIR TAXI-PASSG	TOTAL HOURS, 1600 IN	
			DAMAGE-DESTROYED	OT-	0	0	0		TYPE, NOT INSTRUMENT	
RATED.										
DEPARTURE POINT			INTENDED DESTINATION							
KAPAAU,HAWAII			KAMUELA,HAWAII							
TYPE OF ACCIDENT				PHASE OF OPERATION						
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE						
COLLIDED WITH: TREES				LANDING: POWER-OFF AUTOROTATIVE LANDING						
PROBABLE CAUSE(S)										
ROTORCRAFT - TRANSMISSION ROTOR DRIVE SYSTEM: CLUTCH ASSEMBLY										
MISCELLANEOUS ACTS,CONDITIONS - MATERIAL FAILURE										
TERRAIN - HIGH OBSTRUCTIONS										
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE										
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND										
REMARKS- CLUTCH FAILED FOR UNDET REASON.LND IN GUAVA TREES.										

Full narrative is not available